Improvements and Asphalting to Chikkadinne and surrounding areas in Attur ward No 03 of Yelahanka Satellite town sub Division.

SITE ORDER BOOK

Date :- 25/07/22

Work location :- Chikkadinne and Surrounding areas.

Work done :- Earth work excavation at
3rd Cross.

AE

Date :- 26/07/22

Work location :- Chikkadinne and Surrounding areas.

Work done :- Earth work excavation at
1st Cross.
3rd A Cross
2nd A Cross.

AE

Date :- 27/07/22

Work location :- Chikkadinne and Surrounding areas

Work done :- Earth work excavation at
4th A Cross
1st A Cross.
PCC M10 at 3rd Cross.

AE

Date :- 28/07/22

Work location :- Chikkadinne and Surrounding areas.

Work done :- PCC at 3rd Cross.
1st Cross.

AE.

Date :- 29/07/2022

Work location :- Chikkadinne and surrounding areas

Work done :- Earth work excavation at
Cross Road 1
WO 322
Bottom draft at
1st Cross
3rd Cross.

AE

Date :- 30/07/2022

Work location :- Chikkadinne and surrounding areas.

Work done :- Earth work excavation at
2nd Cross road.

AE

Date :- 01/08/2022

Work location :- chikkadinne and Surrounding areas

Work done :- PCC work [M10] at
3rd A cross [LHS & RHS]
2nd A Cross [LHS & RHS]

WALL Concrete at
3rd Cross [LHS & RHS]

culvert

AE

Date : 02/08/2022

Work location : chikkadinne and Surrounding areas

Work done : Steel work at
3rd 'A' Cross [LHS & RHS]
2nd 'A' Cross [LHS & RHS]

(M10) PCC work at
4th 'A' Cross [LHS & RHS]

Wall Concrete at
1st Cross [LHS & RHS]

GA

AE.

Date : 03/08/2022

Work location : chikkadinne and Surrounding areas.

Work done : Raft work at
3rd 'A' Cross [LHS & RHS]
2nd 'A' Cross [LHS & RHS]

PCC work at
Cross Road 1

Culvet work.

GA

AE.

Date : 04/08/2022

Work location : chikkadinne and Surrounding Area

Work done : Steel work at
Cross Road 1
W0322
Earth work at
1st A Cross
2nd Cross.

AE.

Date : 05/08/2022

Work location : chikkadinne and Surrounding Area

Work done : Wall Concrete at
3rd 'A' Cross
2nd 'A' cross

PCC work at
1st 'A' Cross
2nd Cross

AE.

Date : 06/08/2022

Work location : chikkadinne and Surrounding Area

Work done : Raft work at
W0322
Cross Road 1
Steel work at
1st 'A' Cross Road
2nd Cross Road
Wall Concrete at
4th 'A' Cross Road.

Date : 08/12/2022

Work location : chikkadinne and Surrounding Area

Work done : Earth work at

Main Road.

Raft work at

1ST 'A' cross

2nd 'A' cross.

AE.

AE GA

Date : 10/08/2022

Work location : chikkadinne and Surrounding Area.

work done : Slab

AE.

AE GA

Date : 11/08/2022

work location : chikkadinne and Surrounding Area

Work done : Wall concrete work at

1ST A cross

2nd cross

PCC work at

Main Road (LHS)

AE.

AE GA

12/08/2022

Work location : chikkadinne and Surrounding Area.

Work done : Wall Concrete at

WO 322

1st Cross Road.

1

STeel work at
Main Road (LHS)

AJ GA

Date : 15/08/2022

AE.

Work location : chikkadinne and Surrounding Area

Work done : Culvert slab and Top slab

AJ GA

Date : 16/08/2022

AE.

Work location : chikkadinne and Surrounding Area

Work done : Pcc work at
Main Road (RHS)
Slab laying work at
1ST Cross Road
2nd Cross Road
3rd Cross Road
Raft work at
Main Road (LHS)

AJ GA

Date : 17/08/2022

AE.

Work location : chikkadinne and Surrounding Area

Work done : STeel work at
Main Road (RHS)
Raft work at
Main Road (RHS)
Kerb lining work
3rd Cross Thirumala Nagar.

AJ GA

AE

:08.2022

Work location : chikkadinne and Surrounding Area

Work done : wall Concrete work at
Main Road [LHS & RHS]

AE

A/c 9A

Date : 19/08/2022

Work location : chikkadinne and Surrounding Area.

Work done : Slab laying and pointing work at
1st A cross Road.
2nd A cross Road.
3rd A cross Road.
Culvert excavation at
3rd cross Thirumala Nagar.

AE

A/c 9A

Date : 22/08/2022

Work location : chikkadinne and Surrounding Area.

Work done : Slab lining and pointing work at
Thirumala Nagar.

AE.

A/c 9A

Date : 27/08/2022

Work location : chikkadinne and Surrounding Area

Work done : Slab laying work at
Attur layout, Yelanka New Town.

AE.

A/c 9A

1 Date: 19/09/2022

Work location : chikkadinne and Surrounding area

Work done : Asphalt laying work
Bitumin extrasion work
primier coat work
4th Cross Road.

21/09/2022

Work location : chikkadinne and Surrounding area

Work done : Extraction test at site.

Be work pereming at 4th cross road at chikkadinne.